



IDAHO DEPARTMENT OF
HEALTH & WELFARE

JAMES E. RISCH – Governor
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0036
PHONE: (208) 334-6626
FAX: (208) 364-1888
E-mail: fsb@idhw.state.id.us

September 21, 2006

Cynthia Peterson, Administrator
Spring Creek Manor - Soda Springs
425 Spring Creek Dr
Soda Springs, ID 83276

Dear Ms. Peterson:

On September 6, 2006, a life safety code survey was conducted at Spring Creek Manor - Soda Springs. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

A handwritten signature in black ink, appearing to read 'Mark Grimes', with a long horizontal flourish extending to the right.

MARK GRIMES
Supervisor
Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 13R491	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - ENTIRE BUILDING B. WING _____		(X3) DATE SURVEY COMPLETED 09/06/2006
NAME OF PROVIDER OR SUPPLIER SPRING CREEK MANOR - SODA SPRINGS			STREET ADDRESS, CITY, STATE, ZIP CODE 425 SPRING CREEK DR SODA SPRINGS, ID 83276		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
R9999	<p>Initial Comments</p> <p>The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on September 6, 2006. The surveyor conducting the survey was:</p> <p>Mark P. Grimes, Supervisor Facility Fire Safety & Construction</p>	R9999			

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

6899

0AMS21

If continuation sheet 1 of 1